Qty:



Date

Tuesday, 28/08/2007 9:28:27 AM

User:

Linda Lacelle

Process Sheet

: CU-DAR001 Dart Helicopters Services Customer

Job Number

: 34282

Estimate Number

: 12712

P.O. Number

:NIA

This Issue Prsht Rev.

First Issue

Written By

Comment

Previous Run

: 28/08/2007

S.O. No. : N/A

Type

: SMALL /MED FAB

New Issue 07-02-14 JLM

Drawing Name : WEARPAD

: D35371

Part Number **Drawing Number** . D3537 REV C

Project Number : N/A **Drawing Revision**

:NA Material : 09/09/2007 **Due Date**

100 Um:

Each

Additional Product

Checked & Approved By

Job Number:



Seq. #:

Machine Or Operation:

: Est Rev:A

Description:

M304S16GA 1.0

Comment: Qty.: 0.0788 sf(s)/Unit Total:

7.8750 sf(s)

M304S16GA .063" 304 SS SHEET

Batch: M (05 130

B07-08-78

304/316 .063 Sheet

2.0

WATER JET

Comment: FLOW WATER JET

1-Cut as per Dwg D3537

Dwg Rev: _ C___ Prog Rev: _ ___ PB 07-08-28

2-Deburr if necessary

QC2





B 07-08-28

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

3.0



Comment: SECOND CHECK

BRAKE NO

SECOND CHEC




Comment: NC BRAKE

1-Form as per Dwg D3537 on CNC brake using Jigs DT 8261 and DT 8326.

2-Identify as D3537-1


SB 07/09/19 (20



Date: Tuesday, 28/08/2007 9:28:27 AM User: Linda Lacelle **Process Sheet** Drawing Name: WEARPAD Customer: CU-DAR001-Dart Helicopters Services-Job Number: 34282 Part Number: D35371 Job Number: Seq. #: **Machine Or Operation:** Description: LARGE FAB 1 LARGE FABRICATION RESOURCE 1 6.0 Comment: LARGE FABRICATION RESOURCE 1 Description Qty 2059B Hardcoat 1-Weld as per Dwg D3537 using Jig DT 8210 2-Remove any weld that penetrated through Wearpadif necessary VISUAL WELDING INSPECTION QC9 7.0 Comment: VISUAL WELDING INSPECTION 8.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 9.0 POWDER COATING POWDER COATING M104846 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 10.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE #1 11.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 12.0 QC21 FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE






W D7.10'W







DART AEROSPACE LTD	Work Order:	34282
Description: WEAR PAD	Part Number:	D3537-1
Inspection Dwg: Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

~	Efect Anti-le	Dan Salaras a
X	First Article	Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
08EXOGG. &	100 200. +	PLE XOCE	*			1
.3,500	4/- 1010	3500	X			
4.250	4010	4.254	*		B	
1.965	4010	1.968	¥			
2.795	th .010	2.794	¥			
3.625	1/2 .010	3.638	×			
		4				
1111			-			E
	34					
104800						est on
学工,大学工)	

				1)	
Measured by:	B	Audited by:	en.	Prototype Approval:	Ma
Date:	07-08-28	Date:	09/02/29	Date:	10/00
				- months	

Rev	Date	Change	Revised by	Approved
Α	¥	New Issue	KJ/JLM	

The first